


Maker Workstation Layer Guide 7224


	Dog Holes		Riser Locations
	Top Attach Holes		Side Plate Pockets
	Hold-Down Holes		T-Nut Locations
			Block Holes

3/4"


1/4" **5/16"**



Middle Layer T-Nuts & 1/4" Side Plate Pockets on Bottom



Bottom Layer T-Nuts & 1/4" Side Plate Pockets on Top



Top Layer Countersink Attachment Holes on Top

